



Vibration Vs Capacitance Vs RF Capacitance Level Switch

RF Capacitance Switch

On Condition




OFF Condition




Capacitance Switch

On Condition




OFF Condition




Vibration Switch


On Condition




OFF Condition




OFF (OK)



ON (Error)



OFF (Error)



Sensor 에 분진 짐착에 인한 오류

진동으로 발생한 동굴로 인한 오류

Abnormal Condition

CLIENT	Level Switch 비교		
PLANT NAME			
PROJECT	RF Capacitance 레벨스위치		
FACILITY TITLE			
DRAWING TITLE			
JOB NO.	DWG NO.	REV. NO. A	SHEET NO.

REV-ISION	REV. NO. Δ		DATE	REV. NO. Δ		DATE	REV. NO. Δ		DATE	DESIGNED BY		SCALE	NONE
	REV. NO. Δ			REV. NO. Δ			REV. NO. Δ			APPROVED BY		DATE	13, Aug

아인기술
Ain Engineering Co.